

Annexure D

BUILDING SAFETY CERTIFICATE

No. _____

Dated: _____

It is certified that the existing building Air Force School, Chandan Nagar (name of the building or premises) at G.B.R.D., Air Force Station, Pune-14 (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
school						
No. of Floor(s) in the Block	01	02	01			

The building is owned/occupied by Air Force School, Chandan Nagar (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of _____ (Name of Department/ Govt.) on _____ (date of inspection) in the presence of Mrs. Seema Tiwari (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from _____ for a period of five years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 10 May 24 at Lohegaon (Pune) by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : _____

Designation : (Swami Dhanesh, IDSE)

Name & Address of Department/ Office: EE Garrison Engineer (AF) Lohegaon